

4. Briefly describe . . . type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Limestone was mined from existing benches. No new surface disturbance was caused due to mining.

5. How much additional acreage was disturbed during the past year? **740.83 acres**
6. How much acreage was reclaimed during the past year? **None**

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

Seed bearing horizon (top soil) was stockpiled at the stripping area during 2004 by bulldozer for use in concurrent reclamation of stripping areas.

8. What is the total disturbed acreage of entire project at year's end? As per the revised LMO, the total disturbed acreage, including plant, quarry, strip dump and village is: **819.83 Acres**
9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Mining is planned with similar tonnage requirements to 2005. LMO under review during 2004 and will be finalized in 2005. Soil Survey in spring 2005.

NOTE: Section III., "Additional Information" applies only to **large mining operations.**

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): **Chester Goodson**

Title of Operator: **Plant Manager**

Signature of Operator: 

Date: **21 January 2005**